

Date: 11-November-2015

Time: 15:08:49

Title: **A20 Leybourne/Ditton**

Requested output: **D - Print Crash Report**

Date: 11-November-2015

There were 76 reported crashes resulting in injury

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
1	Road No F834 Grid 570333E Section 083 Ref 158343N	SLIGHT	11/07/2012	4	10:54	L	Dry	Fine			
	New Hythe Lane J/W A20, Larkfield, Kent									Tonbridge and Malling	
V2 Has Overtaken V1 on the Approach to a Set of Traffic Lights and Stopped. V1 Has Been Unable to Stop in Time and Has Hit V2 in the Rear. at the Time of Writing it is Thought V2 Stopped for a Red Light. V1 Has Been Examined and it Has Been Established That the Brakes on the Trailer Were Not Working.							Veh1, agric veh, NW -> SE Veh2, car, NW -> SE			Casualties 1 Vehicles 2	
2	Road No A20 Grid 569994E Section 136 Ref 158319N	SLIGHT	20/07/2012	6	12:32	L	Dry	Fine			GV
	A20 London Road, Aylesford, Kent (Mapped to Police Ref)									Tonbridge and Malling	
Unmarked Police Vehicle in Lane One of Dual Carriageway, Illuminated Blue Lights to Stop a Vehicle Committing a Traffic Offence, Vehicle 2 in Lane Two in Slow Moving Traffic, Vehicle 1 in Same Lane as Vehicle 2. Vehicle 1 Whilst Looking at Blue Lights Collided with Rear of Vehicle 2 Causing Minor Damage as Injury.							Veh1, car, SW -> E Veh2, goods < 3.5t, SW -> E Veh3, car, SW -> E			Casualties 2 Vehicles 3	
3	Road No A20 Grid 570471E Section 141 Ref 158349N	SLIGHT	07/08/2012	3	16:38	L	Dry	Fine		O/TAKE	M/C
	A20, Outside Number 743 London Road, Larkfield, Kent									Tonbridge and Malling	
Veh 1 Filtering Through Slow Moving Traffic, Has Lost Control and Crashed into Back of Veh 2. Drv is Age is Confirmed as Under Age.							Veh1, m/cycle 50 - 125cc, W -> E Veh2, car, W -> E			Casualties 2 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
4	Road No C26 Grid 572441E Section 008 Ref 157972N	SLIGHT	15/08/2012	4	11:25	L	Dry	Fine			M/C
Uc, Hall Road, 100 Metres North of A20 London Road, Maidstone, Kent									Tonbridge and Malling		
Veh 2 was Parked on Hall Road Towards London Road in Line of Traffic Due to Red Lights. Veh 1 Approaching from Behind was Looking Behind and Didn't See Traffic Stopped Looked Back in Front and Saw Traffic Stopped, Tried to Stop but was Too Late and Hit Back of Veh 2 at Low Speed.							Veh1, m/cycle 125 - 500cc, NE -> SW Veh2, car, NE -> SW			Casualties	1
										Vehicles	2
5	Road No A20 Grid 572009E Section 154 Ref 158130N	SLIGHT	29/09/2012	7	12:35	L	Dry	Fine		S.VEH	M/C
A20 London Road J.W Woodlands Rd, Ditton, Maidstone, Kent									Tonbridge and Malling		
Veh 1 was Pulling out of the Junction onto A20 and the Rider Lost Control and Dropped Their Bike							Veh1, m/cycle 125 - 500cc, S -> E			Casualties	1
										Vehicles	1
6	Road No A20 Grid 572789E Section 159 Ref 157738N	SLIGHT	02/10/2012	3	07:05	L	Wet/Damp	Rain		R.TURN	P/C
Hermitage Lane, at the Junction with the A20 London Road, Aylesford, Maidstone.									Tonbridge and Malling		
as V1 (Pedal Cycle) Turned right into Hermitage Lane, it Cut across the Path of V2 which was turning Left, Resulting in a Collision.							Veh1, pedal cycle, W -> S Veh2, car, E -> S			Casualties	1
										Vehicles	2
7	Road No A20 Grid 568776E Section 128 Ref 158275N	SLIGHT	01/11/2012	5	19:35	DRK STL	Dry	Fine			
A20 London Road J/W Oxley Shaw Lane, Leybourne, Kent									Tonbridge and Malling		
both Drivers Believed They Were on Green Lights and Pulled Away Causing both Vehicles to Collide.							Veh1, car, W -> E Veh2, car, W -> E			Casualties	3
										Vehicles	2

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
8	Road No A20 Grid 571048E Section 146 Ref 158468N	SERIOUS	10/11/2012	7	20:15	DRK STL	Wet/Damp	Unknown	N	S.VEH	
	A20, Outside Number 576 London Road, Ditton, Kent									Tonbridge and Malling	PED
Cas Has Come from Jet Petrol Garage and Attempted to Cross Main Road Via a Central Island Crossing, as Cas Stepped into the Road Cas was Struck by Vehicle 1.							Veh1, car, E -> W			Casualties	1
										Vehicles	1
9	Road No A20 Grid 573224E Section 165 Ref 157760N	SLIGHT	28/11/2012	4	21:00	DRK STL	Dry	Fine			M/C
	A20, B C/Way, Slip to M20 Junction 5, Maidstone, Kent									Tonbridge and Malling	
Veh 1 in Lane One of Slip to Roundabout. Veh 2 Pulled up on Offside Intending to Go left at First Exit. as Vehs Pulled Away from Slip, which is Traffic Light Controlled, Veh 1 Went Straight on and Not left and both Vehs Came into Contact. Rider of Veh2 Attempted to Prevent Motorcycle Going Over, which it Still Did, Causing Neck Injury.							Veh1, car, W -> E Veh2, m/cycle > 500cc, W -> N			Casualties	1
										Vehicles	2
10	Road No A20 Grid 571287E Section 147 Ref 158386N	SLIGHT	07/12/2012	6	07:15	DRK STL	Wet/Damp	Fine	E	S.VEH	M/C
	A20, London Road J/W Station Road, Ditton, Maidstone, Kent									Tonbridge and Malling	PED
Veh 1 Travelling A20 London Road. Veh 1 Turned left into Station Road (Ats on Green for Traffic) Pedestrian Crossing Road Whilst out for a Run, Listening to Music on Headphones, Not Wearing Any Reflective Material , Failed to Hear or See Veh1. both Come into Contact, Pedestrian Knocked to Ground, Motorcyclist Fell from Motorcycle							Veh1, m/cycle 50 - 125cc, W -> NE			Casualties	2
										Vehicles	1

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
11	Road No A20 Grid 573260E Section 165 Ref 157780N	SLIGHT	12/01/2013	7	12:20	L	Dry	Fine			
	A20, Spur Road Roundabout, A20 Spur Road, Aylesford, Kent									Tonbridge and Malling	
V1 Intending Heading Towards J5 Roundabout but at Last Minute Turns right Striking V2 which was Also Intending to Travel Towards J5 Roundabout.							Veh1, car, W -> N Veh2, car, W -> N			Casualties 1 Vehicles 2	
12	Road No A20 Grid 573230E Section 165 Ref 157730N	SLIGHT	09/03/2013	7	16:30	L	Dry	Fine			
	A20, London Road, Roundabout J/W M20 Aylesford, Kent									Tonbridge and Malling	
both Vehicles Negotiating Roundabout V1 on Inside of V2. on Reaching J/W A20 London Road Towards Ditton, V1 Failed to Take Exit and Cut across Path of V2 Taking Exit. Contact was Made and Injury Caused. V1 Failed to Stop and Exchange Details, Damage to both Vehicles.							Veh1, car, E -> N Veh2, car, E -> W			Casualties 1 Vehicles 2	
13	Road No A20 Grid 570127E Section 138 Ref 158303N	SLIGHT	11/03/2013	2	17:35	DRK STL	Snow	Snow Wind	N	S.VEH	
	A20 London Road J/W New Road, East Malling, Kent									Tonbridge and Malling	
this is a Non Stop Rtc but from the Description:- C1 Walked into the Road Whilst Traffic Light was Green, C1 Did Not See V1. V1 Sounded Their Horn and Caught C1, Causing a Graze to Their Back.							Veh1, car, E -> W			Casualties 1 Vehicles 1	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
14	Road No A20 Grid 570890E Section 144 Ref 158460N	SLIGHT	25/03/2013	2	17:30	L	Dry	Fine		R.TURN	P/C
A20 London Road J/W Bell Lane, Ditton, Kent									Tonbridge and Malling		
V2 was Travelling Along A20 Towards Maidstone Just Before the Junction with Bell Lane, V1 Turned right into Bell Lane Causing V2 to Hit the Rear of V1. Rider 2 Fell off V2.							Veh1, car, E -> N Veh2, pedal cycle, W -> E			Casualties 1 Vehicles 2	
15	Road No A20 Grid 569630E Section 134 Ref 158230N	SLIGHT	16/04/2013	3	10:00	L	Dry	Fine			
A20 London Road J/W Winterfield Lane, Larkfield, Kent.									Tonbridge and Malling		
Veh 2 was Waiting in a Queue of Traffic at Traffic Lights on London Road at Junction with Winterfield Lane. Veh 1 Approaching from Rear Failed to Stop in Time and Collided with Rear of Veh 2. Veh1 Failed to Exchange Details and Drove off Without Complying with Sec 170 Rta.							Veh1, car, E -> W Veh2, car, E -> W			Casualties 1 Vehicles 2	
16	Road No A20 Grid 572423E Section 157 Ref 157929N	SLIGHT	24/05/2013	6	21:25	DRK STL	Wet/Damp	Fine			GV
A20 London Road, at J/W Mills Road, Aylesford, Kent									Tonbridge and Malling		
V2 Waiting Behind a Car at Traffic Lights. Lights Changed to Green and Car at Front Started to Move off but Stopped Suddenly Causing V2 to Brake Hard. V1, Travelling Behind V2, Did Not Stop and Collided with Rear of V2. V2 Pulled over but V1 Drove Away Without Stopping to Exchange Details.							Veh1, unknown veh type, NW -> SE Veh2, goods < 3.5t, NW -> SE			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
17	Road No A20 Section 127 Grid 568610E Ref 158288N	SERIOUS	25/05/2013	7	10:15	L	Dry	Fine			P/C
A20 London Road, West Malling, Kent (Mapped to Police Confirmed Location 568636,158291)									Tonbridge and Malling		
Veh1 Travelling Along London Road, West Malling in Direction of Larkfield. Veh 1 Has Somehow Clipped Wing Mirror with Veh 2. Causing Veh 2 to Fall off Pedal Cycle. on Seeing this Veh1 Has Pulled over to Stop. Unfortunately this was Directly in the Path of Veh 3. Veh 3 Has Collided with Rear and Fallen Off.							Veh1, car, W -> E Veh2, pedal cycle, W -> E Veh3, pedal cycle, W -> E			Casualties 2 Vehicles 3	
18	Road No A20 Section 138 Grid 570091E Ref 158322N	SLIGHT	08/06/2013	7	13:11	L	Dry	Fine		R.TURN	
A20, London Road J/W B and Q , Larkfield, Maidstone, Kent									Tonbridge and Malling		
Veh 1 was Leaving B & Q and Crossing the Live Lanes of Traffic on the A20 turning Right. a Bus Had Stopped in the N/S Lane on the A20 for a Red Traffic Light and Had Stopped Short Because of the Road Markings Showing 'Keep Clear'. Veh 1 then Pulled onto the A20 with a Clear View of the Traffic Coming from the right and Pulled into the Path of Veh 2 and a Collision Occured.							Veh1, car, N -> W Veh2, car, W -> E			Casualties 2 Vehicles 2	
19	Road No A20 Section 159 Grid 572787E Ref 157745N	SLIGHT	24/06/2013	2	12:30	L	Dry	Fine		R.TURN	HGV
London Rd at Junction with Hermitage Lane, Maidstone, Kent									Tonbridge and Malling		
Veh 1 and Veh 2 both turning right from Hermitage Lane into London Rd, (Veh 2 in Middle Lane and Veh 1 in Outside Lane). as both Vehicle Proceeded Through Lights, Veh 1 Did Not Follow Correct Path and Moved into Middle Lane, Colliding with Veh 2 both Parties Stopped and Exchanged Details, but Driver of Veh 2 Suffered Minor Injury.							Veh1, goods 3.5 - 7.5t, S -> E Veh2, car, S -> E			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
20	Road No A20 Section 145	Grid 570962E Ref 158471N	SLIGHT	05/07/2013	6	17:32	L	Dry	Fine		
	London Road O/S Service Station, Ditton, Kent									Tonbridge and Malling	
this is an Rtc Whereby Vehicle 1 Has Pulled out from a Service Station and Collided with Vehicle 2 Who Had right of Way on the Main Road. Minor Injury Only to both Drivers and Section 170 Complied With.							Veh1, car, S -> W Veh2, car, E -> W			Casualties 2 Vehicles 2	
21	Road No C349 Section 001	Grid 571400E Ref 158440N	SLIGHT	19/07/2013	6	08:43	L	Dry	Fine		M/C
	Station Road 100M from Jw London Road at Entrance to Sports Ground, Ditton,Kent									Tonbridge and Malling	
V1 Has Passed V2 on the Offside as it was turning right							Veh1, m/cycle 125 - 500cc, NE -> SW Veh2, car, NE -> NW			Casualties 1 Vehicles 2	
22	Road No A20 Section 139	Grid 570245E Ref 158318N	SERIOUS	23/08/2013	6	17:30	L	Dry	Fine	N	S.VEH
	A20, London Road 200M East of J/W New Road, Larkfield, Kent.									Tonbridge and Malling	
Veh 1 was Travelling West Along A20 London Road when Pedestrian Ran out from the Pavement into the Road and Directly into the Path of Veh 1.							Veh1, car, E -> W			Casualties 1 Vehicles 1	
23	Road No A20 Section 142	Grid 570630E Ref 158395N	SERIOUS	02/09/2013	2	18:02	L	Dry	Fine		P/C
	A20 London Road J/W Bradbourne Lane, Ditton, Kent									Tonbridge and Malling	
V1 Has Entered Main Road from Footpath, for Unknown Reason, into the Path of V2. V1 and V2 Have then Collided							Veh1, pedal cycle, NE -> SW Veh2, car, SW -> NE			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
24	Road No A20 Section 141 Grid 570386E Ref 158323N	SLIGHT	17/09/2013	3	08:00	L	Dry	Fine			PSV
A20 London Road Near J/W New Hythe Lane, Larkfield, Kent									Tonbridge and Malling		
V2 was in the Nearside Lane. V1 was in the Middle Lane. the Road Narrows So V1 Indicated to Filter in Front of V2. at Tht Point a Bus (V3) Pulled out from the Bus Stop which Caused V2 to Collide with V1. no Details of Driver 2.							Veh1, car, E -> W Veh2, car, E -> W Veh3, bus or coach, E -> W			Casualties 2 Vehicles 3	
25	Road No A20 Section 149 Grid 571473E Ref 158337N	SLIGHT	29/09/2013	1	16:35	L	Dry	Unknown		R.TURN	
A20, London Road, Ouside Papas Fish Bar, Ditton, Kent									Tonbridge and Malling		
Veh 1 is Following Behind Veh 2. Veh 2 Has Stopped to Turn into the Chip Shop and Driver of Veh 1 Has Not Seen in Time. Veh 1 Has Collided with the Rear of Veh 2 Causing Minor Damage.							Veh1, car, NW -> SE Veh2, car, NW -> S			Casualties 2 Vehicles 2	
26	Road No A20 Section 140 Grid 570332E Ref 158334N	SLIGHT	21/10/2013	2	10:40	L	Wet/Damp	Rain		R.TURN	
A20, London Road J/W New Hythe Lane, Larkfield, Kent									Tonbridge and Malling		
V2 Has Slowed down Due to Reversing Vehicle. V1 Has Followed V2 but Failed to Brake and Collided with V2.							Veh1, car, N -> W Veh2, car, N -> W			Casualties 1 Vehicles 2	
27	Road No A20 Section 165 Grid 573275E Ref 157729N	SLIGHT	30/10/2013	4	07:10	L	Wet/Damp	Fine			M/C
A20 London Road, Aylesford, Kent									Tonbridge and Malling		
Veh 1 Has Been Filtering Between Traffic on Approach to Coldharbour Roundabout, the Lights Have Changed. Veh 1 Has Filtered Through Intending to Travel down the A20 but Has Collided with Veh 2 on the Offside Rear.							Veh1, m/cycle 50 - 125cc, SE -> W Veh2, car, SE -> W			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvr
O/TAKE Overtaking Manoeuvr
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
28	Road No A20 Grid 573269E Section 164 Ref 157850N	SLIGHT	31/10/2013	5	12:05	L	Wet/Damp	Rain			
	A20, 50 Metres North of Roundabout with London Road, Aylesford, Maidstone, Kent									Tonbridge and Malling	
V2 Failed to Observe V1 Stopping in Slow Moving Traffic and Hit V2 in Rear							Veh1, car, S -> N Veh2, car, S -> N			Casualties 1 Vehicles 2	
29	Road No A20 Grid 571752E Section 151 Ref 158245N	SLIGHT	02/11/2013	7	14:55	L	Wet/Damp	Fine			
	A20, London Road, Outside Number 428, Ditton, Aylesford.									Tonbridge and Malling	
V2 was Stationary Waiting for the Vehicle in Front to Turn Right, when V1 Has Collided with the Rear of V2 Due to D1 Suffering a Medical Episode and Being Unable to Stop in Time.							Veh1, car, NW -> SE Veh2, car, NW -> SE			Casualties 1 Vehicles 2	
30	Road No F121 Grid 572448E Section 012 Ref 157779N	SERIOUS	04/11/2013	2	12:05	L	Dry	Fine	W	S.VEH	
	Mills Road, Sainsburys Car Park, Aylesford, Kent									Tonbridge and Malling	
Whilst Crossing the Road Casualty 1 Has Collided with Veh 1. Casualty Has Serious Injuries as a Result of the Collision.							Veh1, car, N -> S			Casualties 1 Vehicles 1	
31	Road No A20 Grid 571480E Section 149 Ref 158339N	SLIGHT	20/11/2013	4	20:12	L	Wet/Damp	Rain		R.TURN	
	A20, Outside Papas Restaurant, Aylesford, Kent									Tonbridge and Malling	
Veh 2 Driving Along London Road, Towards Maidstone. Veh 2 Went to Turn into Papa's Fishbar, Therefore Slowed Down. Veh 1 Travelling Behind Stated Did Not See Veh 2 Indicate, Slammed Brakes On, Collided with Veh 2, Hitting the Rear. both Vehicles Negative Eba.							Veh1, car, NW -> SE Veh2, car, NW -> SW			Casualties 4 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
32	Road No A20 Grid 573281E Section 165 Ref 157778N	SLIGHT	09/12/2013	2	10:50	L	Dry	Fine			HGV
A20, London Road Jw Coldharbour Lane, Aylesford, Kent									Tonbridge and Malling		
Veh1 and Veh2 Negotiating Roundabout on A20 London Road After Exiting M20 at Jct 3. Veh1 was in Outside Lane of Roundabout, Veh2 on the Inside. Vehs Collided Whilst Negotiating Roundabout.							Veh1, goods > 7.5t, NW -> SE Veh2, car, NW -> SE			Casualties 1 Vehicles 2	
33	Road No A20 Grid 573286E Section 165 Ref 157780N	SLIGHT	22/01/2014	4	14:48	L	Wet/Damp	Fine			
A20 London Road, Aylesford, Kent									Tonbridge and Malling		
V2 Had Stopped at Red Ats on A20 London Road, Aylesford. V1 Has Failed to Stop in Time Hitting V2							Veh1, car, W -> E Veh2, car, W -> E			Casualties 1 Vehicles 2	
34	Road No A228 Grid 568737E Section 161 Ref 158087N	SLIGHT	01/02/2014	7	14:42	L	Wet/Damp	Rain		R.TURN	
A228, West Malling Bypass 10M from Jw A20 London Road, Slip onto A228, Tonbridge, Kent.									Tonbridge and Malling		
Veh 1 was at Red Traffic Light Waiting to Turn right onto A228 from A20, the Weather Conditions Were Wet and Raining. There Are Two Sets of Traffic Lights, Driver of Veh 1 Has Seen Them Change and Pulled out Without Looking, Driver was Not Looking at the Correct Lights and the Ones for Were in Fact Red Causing Veh 1 to Pull out in Front of Veh 2 Who was Accelerating Away from the Junction as the Lights Were Green Causing both Vehicles to Crash.							Veh1, car, NE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
35	Road No A20 Grid 570890E Section 144 Ref 158460N	SLIGHT	07/02/2014	6	12:00	L	Dry	Fine			
	A20 London Road J/W Bell Lane, Ditton, Kent									Tonbridge and Malling	
V1 Appears to Have Had a Medical Episode, Drove down the Chevrons and then Clipped the Central Traffic Island, Skidded and Collided with V2. V1 Has then Span and Struck the Railings							Veh1, car, W -> E Veh2, car, E -> W			Casualties	1
										Vehicles	2
36	Road No A20 Grid 572780E Section 159 Ref 157730N	SLIGHT	18/02/2014	3	18:00	L	Wet/Damp	Unknown			
	A20 London Road, Junction with B2246 Hermitage Lane, Maidstone, Kent									Tonbridge and Malling	
V2 (Pedal Cycle) at the Crossing on London Road, Towards Hermitage Lane Waiting for the Green Man, a Van was Stopped as the Green Man Came on and V2 Started to Ride across in Front of the Van. V1 in the Second Lane Did Not Stop and Struck V2 Front Wheel Dragging the Bike and Throwing Rider into the Air Making Impact with the Ground.							Veh1, car, E -> W Veh2, pedal cycle, S -> N			Casualties	1
										Vehicles	2
37	Road No A20 Grid 573389E Section 166 Ref 157664N	SLIGHT	23/02/2014	1	11:50	L	Dry	Fine			
	London Road, Outside the Police Traffic Hq, Aylesford									Tonbridge and Malling	
All 3 Vehicles Travelling from Maidstone Towards Aylesford when Traffic in Front Stopped. V1 then Collided with the Rear of V2 and then V3 Collided with the Rear of V1.							Veh1, car, SE -> NW Veh2, car, SE -> NW Veh3, car, SE -> NW			Casualties	1
										Vehicles	3

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
38	Road No A20 Grid 572771E Section 159 Ref 157759N	SLIGHT	28/03/2014	6	09:50	L	Dry	Fine			
A20 London Rd J/W B2246 Hermitage Lane, Aylesford, Kent									Tonbridge and Malling		
All Parties Have Been Spoken to and it Would Appear no One Can Give a Completely Accurate Account as What Has Actually Happened. it Would Appear That an Unknown Secas Vehicle was on an Immediate Call Going from Hermitage Lane turning right on to A20 London Rd, Maidstone, Despite the Traffic Light Being Green, V1 Has Stopped Allowing the Secas Vehicle right of Way, V2 is Believed to Have then Hit V1 and V3 Has Hit V2.							Veh1, car, W -> E Veh2, car, W -> E Veh3, car, W -> E			Casualties 1 Vehicles 3	
39	Road No A20 Grid 570010E Section 137 Ref 158315N	SLIGHT	01/04/2014	3	13:30	L	Dry	Unknown		R.TURN	
A20, London Road, Larkfield, Kent									Tonbridge and Malling		
V1 Travelling from Ditton Towards West Malling, V2 Travelling in Opposite Direction V1 Has Gone to Pull into the Petrol Station V2 Swerved to Avoid but V1 Collided with V2							Veh1, car, E -> N Veh2, car, W -> E			Casualties 2 Vehicles 2	
40	Road No A20 Grid 572842E Section 160 Ref 157723N	SLIGHT	13/04/2014	1	12:30	L	Dry	Fine			
A20, London Road, Aylesford, Kent (Mapped to 572840/157710)									Tonbridge and Malling		
V2 Stationary in Queue of Traffic Waiting at Red Automatic Traffic Signal Junction. V1 Drove into the Rear of V2 at Low Speed Passenger in V1 Minor Injuries. S170 Exchanged.							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
41	Road No A20 Grid 568880E Section 130 Ref 158230N	SLIGHT	02/05/2014	6	10:10	L	Dry	Fine			PSV
London Road, Just Past Slip Road / West Malling Bypass Leybourne Kent									Tonbridge and Malling		
Veh 2 (Bus) was on the London Road Veh 1 was on Offside of Veh 2. There was an Island in the Centre of the Road Causing Veh 1 to Pull over and Hit the Offside of the Veh 2. Veh 1 Drove Away. One of the Passenger Hurt Forehead when the Bus Applied its Brakes and the Driver Has a Sore Neck.							Veh1, car, W -> E Veh2, bus or coach, W -> E			Casualties 2 Vehicles 2	
42	Road No A20 Grid 572210E Section 155 Ref 158050N	SLIGHT	11/05/2014	1	23:26	DRK STL	Dry	Fine		+VE	PSV
A20, London Road J.W Shop Layby, Aylesford, Kent									Tonbridge and Malling		
V2 Travelling East Along London Road. V1 was Travelling the Same Direction at Speed Failing to See V2 and Collided with the Rear of V2 Causing Damage to both Vehicles. Driver of V1 Spoke to Driver of V2 but Did Not Give Any Details. Driver V1 then Drove off at Speed. Believed V1 Passenger was Injured and Located in Hall Road.							Veh1, car, W -> E Veh2, car, W -> E			Casualties 1 Vehicles 2	
43	Road No A20 Grid 568788E Section 128 Ref 158274N	SLIGHT	16/05/2014	6	21:08	DRK STL	Dry	Fine		R.TURN	PSV
A20, London Road Jw A228, Ashton Way, Leybourne, West Malling.									Tonbridge and Malling		
V1 is Alleged to Have Come Through a Red Light and Turned into the Path of V2 Causing a Collision.							Veh1, car, S -> E Veh2, car, N -> S			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
44	Road No A20 Grid 572477E Section 157 Ref 157873N	SLIGHT	20/05/2014	3	09:40	L	Dry	Fine			
A20, London Road, 5 Metres North J/W Mills Road, Aylesford, Kent									Tonbridge and Malling		
Veh 1 was Stationary at Traffic Lights on London Road J/W Mills Road, Aylesford Behind Veh 2. as the Lights Turned Green Veh 1 Went to Move off Before Veh 2, Causing Veh 1 to Hit into the Rear of Veh 2.							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	
45	Road No A20 Grid 569305E Section 131 Ref 158254N	SLIGHT	23/05/2014	6	13:45	L	Dry	Fine		S.VEH	
A20 London Rd J.W Rectory Lane South, Leybourne, Kent									Tonbridge and Malling		
Veh 1 Travelling down the A20 Towards West Malling from Ditton. Veh Began to Swerve Before Coming off the Road.							Veh1, car, E -> W			Casualties 2 Vehicles 1	
46	Road No A20 Grid 571231E Section 146 Ref 158403N	SLIGHT	23/07/2014	4	10:35	L	Dry	Fine			P/C
A20, London Road, Approx 100M West of Jw Station Road, Larkfield, Maidstone									Tonbridge and Malling		
Police Vehicle Travelling East on A20 Towards Aylesford Using Emergency Lights and Sirens in Response to an Immediate Alarm Call. Traffic Had Pulled over to the Nearside to Allow the Marked Police Car to Pass. this Blocked the Cycle Lane. Cyclist Failed to Slow in Time and Avoided the Cars by Hitting the Kerb. this Caused Rider to Fall off Bike at Very Low Speed Causing Very Minor Injuries.							Veh1, car, NW -> SE Veh2, pedal cycle, NW -> SE Veh3, car, NW -> SE			Casualties 1 Vehicles 3	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
47	Road No A228 Grid 568748E Section 161 Ref 158102N	SLIGHT	05/08/2014	3	19:00	L	Dry	Fine		R.TURN	
A228, Ashton Way J/W A20 London Road, West Malling, Kent									Tonbridge and Malling		
V1 was Travelling Along A228 Towards Kings Hill from Direction of M20. V2 was in Lane 4 of 4 turning right from A228 to A20 at Leybourne at Red Traffic Lights. as Traffic Lights Turned Green in Favour of V2 it Began to Turn right when V1 Went Through Red Traffic Light Hitting V2 to Nearside Spinning it and Causing it to Overturn. V1 and V2 Blocked Carriageway and both Drivers Sustained Minor Injuries.							Veh1, car, NW -> SE Veh2, car, SE -> NE			Casualties	2
										Vehicles	2
48	Road No A20 Grid 571992E Section 153 Ref 158134N	SLIGHT	05/08/2014	3	09:20	L	Dry	Fine		R.TURN	
A20, London Road Jw Teapot Lane, Ditton, Aylesford.									Tonbridge and Malling		
V1 Has Turned right Without Looking from Teapot Lane into London Road and Straight into the Path of V2 Causing a Collision.							Veh1, car, N -> NW Veh2, car, NW -> SE			Casualties	1
										Vehicles	2
49	Road No A20 Grid 570171E Section 139 Ref 158313N	SLIGHT	16/08/2014	7	13:20	L	Dry	Fine			P/C
A20, London Road, Outside Tesco Express, Larkfield, Aylesford.									Tonbridge and Malling		
V1 (Pedal Cycle) Has Come out of Tesco onto the A20, and Straight into the Path of V2 which Had no Chance to Avoid a Collision.							Veh1, pedal cycle, N -> S Veh2, car, E -> W			Casualties	1
										Vehicles	2

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
50	Road No A20 Grid 571762E Section 152 Ref 158238N	SLIGHT	20/08/2014	4	14:25	L	Dry	Fine			
A20, London Road, Outside House Number 426, Maidstone, Kent.										Tonbridge and Malling	
V2 is a Car Travelling Along A20 Towards Maidstone when Braked to Stop Due to Slowing/Stopping Traffic Directly in Front. V1 was Travelling Directly Behind V2 and Collided into the Rear of V2 Causing Damage to both Vehicles and Injuries to All Occupants of Both.							Veh1, car, NW -> SE Veh2, car, NW -> SE			Casualties 3 Vehicles 2	
51	Road No A20 Grid 571878E Section 152 Ref 158179N	SLIGHT	22/08/2014	6	12:18	L	Dry	Fine			
A20 London Road Pedestrian Crossing, Ditton, Kent										Tonbridge and Malling	
D1 was in a Line of Vehicles, was Distracted and Failed to Observe That the Vehicles in Front Had Stopped and Failed to Stop in Time Hitting V2							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	
52	Road No A20 Grid 572971E Section 161 Ref 157723N	SLIGHT	01/09/2014	2	08:20	L	Dry	Fine			HGV
A20 London Road, 50 Metres East of London Road East, Aylesford, Kent										Tonbridge and Malling	
Veh 2 was Stationary Broken down on A20 Heading from Aylesford Towards Maidstone, in the left Hand Lane - Lane1. Veh 1 an Hgv Going in the Same Direction Did Not Stop and Went into the Back of Veh 2.							Veh1, goods > 7.5t, W -> E Veh2, car, P -> P			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
53	Road No A20 Grid 571358E Section 147 Ref 158374N	SLIGHT	11/09/2014	5	01:27	DRK STL	Dry	Fine			
A20 London Road at Junction with Station Road, Ditton, Kent									Tonbridge and Malling		
V2 Travelling A20 Towards Maidstone from Larkfield, as V2 Has Passed Through Ditton Crossroads V1 Has Approached the Slip Lane from Station Road onto A20. V1 Has Not Stopped at the Give Way and Proceeded onto A20 into the Path of V2. V2 Has then Collided with V1. both Vehicles Stopped. Driver of V1 Got out and Approached V2. the Driver Took Photos, Driver of V2 Asked for Ambulance. V1 Driver Returned to Vehicle and Drove Away.							Veh1, car, W -> E Veh2, car, W -> E			Casualties 1 Vehicles 2	
54	Road No A20 Grid 570330E Section 140 Ref 158327N	SLIGHT	04/10/2014	7	16:46	L	Wet/Damp	Fine		R.TURN	
A20, London Road Jw New Hythe Lane, Larkfield, Kent									Tonbridge and Malling		
V1 Has Driven out from New Hythe Lane turning right onto A20. V1 Beleived to Have Travelled Through a Red Light and as a Result V2 Travelling Along London Road Has Passed Through a Green Light Colliding with V2							Veh1, car, N -> W Veh2, car, W -> E			Casualties 3 Vehicles 2	
55	Road No A20 Grid 572591E Section 158 Ref 157835N	SLIGHT	14/11/2014	6	06:40	DRK STL	Wet/Damp	Rain			
A20 London Road, 300 Metres West of B2248 Hermitage Lane, Maidstone, Kent									Tonbridge and Malling		
Veh 2 was in left Hand Lane, Heading Towards Hermitage Lane. Veh 1 Came Alongside Veh 2. D2 Stopped Vehicle and Wound down Window, and Asked D1 Why D1 was Driving So Badly. D1 Stated Thought Veh 2 Had Hit D1 Vehicle. D2 Denied this and D1 Apologised. D1 then Rammed Veh 1 into Veh 2 Before Driving Off. D2 is Slightly Injured. D2 Insists this was a Deliberate Act.							Veh1, car, W -> E Veh2, car, W -> E			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
56	Road No A20 Grid 572008E Section 154 Ref 158132N	SLIGHT	14/11/2014	6	10:15	L	Wet/Damp	Rain		R.TURN	GV
A20 London Road / Woodlands Road, Ditton, Aylesford, Kent									Tonbridge and Malling		
Veh1 was Travelling Along Woodlands Road Towards London Road (A20). Veh2 Travelling Along the A20 Towards the Junction with Woodlands Road Displaying its left Hand Indicator. Veh1 Has Entered the Main Road (A20) and Veh2 Has Collided with Veh1 as it left Woodlands Road to Turn right onto the A20. it is Possible That Veh1 Driver Has Seen Veh2 Displaying its left Hand Indicator and Presumed That it was Going to Turn off the A20 onto Woodlands Road which it Did Not.							Veh1, car, S -> E Veh2, goods < 3.5t, E -> W			Casualties 1 Vehicles 2	
57	Road No A20 Grid 570902E Section 144 Ref 158473N	SLIGHT	01/12/2014	2	08:07	L	Dry	Fine	U	S.VEH	M/C
A20 Near Jw Bell Lane, Ditton, Kent									Tonbridge and Malling		PED
V1 was Travelling in Centre of Road Passed Stationary Traffic - Pedestrian Stepped out from in Between Cars and Been Hit by V1 - Rider and Pedestrian Injured.							Veh1, m/cycle 50 - 125cc, W -> E			Casualties 2 Vehicles 1	
58	Road No A20 Grid 570112E Section 138 Ref 158317N	SLIGHT	15/12/2014	2	07:20	DRK STL	Wet/Damp	Fine		R.TURN	GV
A20 London Road / New Road, East Malling, Kent									Tonbridge and Malling		
Veh1 was Travelling Along the A20 London Road from Aylesford in the Direction of Wrotham. Veh2 was Held at a Red Traffic Light at the End of New Road, JW the A20. when Veh2's Light Has Gone to Green, it Has Proceeded into the Junction in Order to Turn Right. However Veh1 Has Driven Straight into the Side of Veh2 Mid Junction. an Independent Witness Claims That Veh1 Went Through a Red Light which is Also What Driver of Veh2 States.							Veh1, car, E -> W Veh2, goods < 3.5t, S -> E			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
59	Road No A20 Grid 571266E Section 147 Ref 158391N	SLIGHT	19/01/2015	2	16:20	L	Dry	Fine	N	S.VEH	
A20, London Road Jw New Road, Ditton, Kent									Tonbridge and Malling	PED	
Slow Moving Traffic Along A20, London Road in both Directions. V1 Approaching Traffic Lights, A20 Jw New Road, Ditton. Green Light, Therefore Followed Flow of Traffic West Malling Towards Maidstone. Pedestrian Crossing Road as Failed to Comply with Signal and Ran out on a Red Crossing Light Resulting in Collision with V1							Veh1, car, NW -> SE			Casualties 1 Vehicles 1	
60	Road No A20 Grid 572450E Section 157 Ref 157909N	SLIGHT	19/01/2015	2	15:05	L	Dry	Unknown		S.VEH	PSV
A20 J.W Hall Road, with Homebase Bus Stop, Aylesford, Kent									Tonbridge and Malling		
Veh 1 Pulled Away from the Bus Stop. the Driver Wasnt Aware of Any Incident. Arriva Has Recieved a Letter from a Pssenger That was on the Bus at the Time. Passenger is Saying They Were Injured when the Bus Pulled Away. Full Details Not Known.							Veh1, bus or coach, NW -> SE			Casualties 1 Vehicles 1	
61	Road No A20 Grid 570328E Section 140 Ref 158315N	SLIGHT	23/02/2015	2	08:05	L	Dry	Fine			
A20, London Road Jw New Hythe Lane, Larkfield, Aylesford.									Tonbridge and Malling		
V's 2, 3, and 4 Were Stationary in a Queue of Traffic when V1 Has Collided with the Rear of V2, Pushing V2 into V3, and V3 into V4.							Veh1, car, E -> W Veh2, car, E -> W Veh3, car, E -> W Veh4, car, E -> W			Casualties 2 Vehicles 4	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
62	Road No A20 Grid 572329E Section 156 Ref 157989N	SLIGHT	19/03/2015	5	14:07	L	Dry	Fine			HGV
	A20 London Road, Aylesford, Kent									Tonbridge and Malling	
V1 Has Been Driving Along A20 Towards Aylesford Village. D1 Has Failed to See V2 in Their Blind Spot. V1 Has Moved from Outside of a Filter Lane, across and Collided with V2. this Has Spun V2 into Approaching Traffic. V3 was Travelling in Opposite Direction and Hit by V2. S170 Complied.							Veh1, goods > 7.5t, SE -> NW Veh2, car, SE -> NW Veh3, car, NW -> SE			Casualties 1 Vehicles 3	
63	Road No A20 Grid 570034E Section 137 Ref 158317N	SLIGHT	23/03/2015	2	09:40	L	Dry	Fine		S.VEH	M/C
	A20, London Road, Outside Tesco's, Larkfield, Kent									Tonbridge and Malling	
V1 was Travelling Along A20 Towards Maidstone. as Approaching Traffic Light Junction, Vehicles in Front Started to Brake. V1 Used Only Front Brake which Caused Rider to Fall off Bike. no Other Vehicles Involved or Impacted. Injuries Are Minor and Consisting of Bruising and Grazing.							Veh1, m/cycle <= 50cc, W -> E			Casualties 1 Vehicles 1	
64	Road No A20 Grid 570571E Section 141 Ref 158377N	SLIGHT	24/03/2015	3	18:10	L	Dry	Fine			M/C
	A20 London Road Within 20 Metres East of Walnut Tree Court, Larkfield, Kent									Tonbridge and Malling	
V2 (Motorcycle) was Riding Towards Ditton Along A20 London Road, Larkfield. as V2 Approached a Lay-By to Their Nearside, V1 Pulled out to Turn in the Road. V2 Collided with the Side of V1.							Veh1, car, SW -> SW Veh2, m/cycle 125 - 500cc, SW -> NE			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
65	Road No A20 Grid 570102E Section 138 Ref 158306N	SLIGHT	23/04/2015	5	14:19	L	Dry	Fine		R.TURN	
A20, London Road J/W New Road, Ditton, Kent									Tonbridge and Malling		
Veh 1 was Travelling from New Road turning right into London Road. Veh 2 was Travelling Along London Road Veh 1 and Veh 2 Crossed Paths as Someone Would Have Been Against a Red Traffic Light as the Collision Occurred.							Veh1, car, S -> E Veh2, car, E -> W			Casualties 4 Vehicles 2	
66	Road No A20 Grid 572448E Section 157 Ref 157892N	SLIGHT	01/05/2015	6	19:30	L	Dry	Fine		R.TURN	
Mills Road, Quarry Wood, Aylesford, Kent									Tonbridge and Malling		
V2 Stopped at the Traffic Lights Along Mill Road. V1 Went into the Back of V2. V2 was in the Middle Lane of A20 London Road, Indicated and Pulled into right Lane to Go to Hall Road, Aylesford. Lights Were Red on Approaching right Lane then Changed Green. V2 Pulled Away and V1 Went into the Back of V2. V1 Driver Stated That V2 Stopped Quickly Causing Them to Go into Their Back.							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 3 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
67	Road No A20 Grid 568773E Section 128 Ref 158274N	SLIGHT	08/05/2015	6	17:09	L	Wet/Damp	Rain			
London Road East of Castle Way, Leybourne, West Malling, Kent									Tonbridge and Malling		
V1 was on Roundabout and Came off Continuing Along London Road Heading East. a Couple of Cars Were Jutting out onto the Roundabout and So V1 Sped up and Went Round Them. V1 Approached the Crossroads, London Road A20 Jw Castle Way. this Junction is Controlled by Traffic Lights. V2 was Already in the Yellow Box Junction on Castle Way Heading North to South onto Ashton Way. V1 Went Through 2 Red Lights and Collided with V2 Driver's Side							Veh1, car, W -> E Veh2, car, N -> S			Casualties 1 Vehicles 2	
68	Road No F834 Grid 570526E Section 083 Ref 158385N	SLIGHT	15/05/2015	6	10:00	L	Dry	Fine			
Larkfield Road, Outside Natwest Bank, Aylesford, Larkfield, Kent									Tonbridge and Malling		
V2 was Parked Stationary at the End of a Row of Parked Vehs. Driver and Passenger Were Inside. V1 was Driving Past the Parked Vehicles (On left Hand Side of the Road). V1 Back in Too Soon, Hitting N/S Rear of V2. D2 Wrote down Index no of V1, Witnesses Also Noted Index No. Natwest Bank Have Cctv Evidence but Will Only Keep it for 60 Days from 15/05/15. D2 Didn't Realise They Had to Report this Incident.							Veh1, car, N -> S Veh2, car, P -> P			Casualties 2 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
69	Road No A20 Grid 571462E Section 149 Ref 158339N	SLIGHT	16/05/2015	7	17:17	L	Dry	Fine			M/C
A20 London Road (O/S 498), Ditton, Aylesford, Kent									Tonbridge and Malling		
V1 was Travelling Along the A20 Towards Aylesford and the British Legion Village when V2 Has Slowed down and Stopped in Front of Them. V1 Has Not Stopped in Time and Despite Trying to Avoid Contact, V1 Has Driven into the Rear of V2. V1 Has then Made Minor Contact with V3 which was Parked and Unattended at the Side of the Road O/S 498. Minor Injuries to Drivers of V1 and 2 Only							Veh1, m/cycle 50 - 125cc, W -> E Veh2, car, W -> E Veh3, car, P -> P			Casualties 2 Vehicles 3	
70	Road No A20 Grid 570613E Section 142 Ref 158383N	SLIGHT	21/05/2015	5	17:37	L	Dry	Fine			
A20, London Road, Jw Bradbourne Lane, Ditton, Kent (Mapped to Grid Ref)									Tonbridge and Malling		
both Vehs Were Travelling Westbound on the A20. D1 Saw the Traffic ahead Slowing but Failed to Do So in Time Resulting in Their Front N/S Colliding with the Rear of V2 Causing Damage to V2 and Neck Injury to D2.							Veh1, car, E -> W Veh2, car, E -> W			Casualties 1 Vehicles 2	
71	Road No A20 Grid 572732E Section 158 Ref 157749N	SLIGHT	23/05/2015	7	10:34	L	Dry	Fine			HGV
A20 London Road, 50 Metres from Jw B2246 Hermitage Lane, Aylesford, Kent									Tonbridge and Malling		
Vehs 1,2,3 and 4 Have All Been Travelling in the Same Direction Along A20 London Road, M20 Towards Quarry Wood. V1 and V2 in Lane 2 of 2 and V3 and 4 Were in Lane 1 of 2. V1 and V2 Moved Lane 2 of 2 to 1 of 2. V3 Stopped Due to Red Lights and Traffic Ahead. V2 Stopped. Driver of V1 was Looking in Mirror and Failed to Stop in Time Hitting V2 Pushing it into V3. V4 Failed Also to Stop and Hit Rear of V1.							Veh1, goods 3.5 - 7.5t, E -> NW Veh2, car, E -> NW Veh3, car, E -> NW Veh4, car, E -> NW			Casualties 2 Vehicles 4	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
72	Road No A20 Grid 570088E Section 138 Ref 158319N	SLIGHT	28/05/2015	5	19:30	L	Dry	Fine		R.TURN	P/C
A20, London Road Close to Jw New Road, Larkfield, Kent									Tonbridge and Malling		
V1 Has Been turning right out of the Petrol Station on to the A20. Driver's View Has Been Obscured by another Vehicle which was Stationary at the Entrance to Petrol Station. V1 Pulled out and V2 which was Travelling Along A20 Has Collided with the Front of V1.							Veh1, car, N -> W Veh2, pedal cycle, W -> E			Casualties 1 Vehicles 2	
73	Road No A20 Grid 570117E Section 138 Ref 158308N	SLIGHT	04/06/2015	5	07:53	L	Dry	Fine		R.TURN	
A20 London Road Jw New Road, Larkfield, Kent									Tonbridge and Malling		
V1 was Driving Along London Road Towards Leybourne, Intending to Continue Ahead. V2 was Driving Along London Road Towards Ditton Intending to Turn right onto New Road. V1's Traffic Light was on Red with a Green Filter Light. V1 Continued ahead and Collided with V2. D2 Taken to Pembury Hospital and Later Released with Bruising Only.							Veh1, car, E -> W Veh2, car, W -> S			Casualties 1 Vehicles 2	
74	Road No A20 Grid 573064E Section 162 Ref 157709N	SLIGHT	13/06/2015	7	13:30	L	Dry	Fine			
A20 London Road, Maidstone, Kent (Mapped to 573060 / 157710)									Tonbridge and Malling		
Vehicles Travelling on A20 in Heavy Traffic Conditions, Slow Moving Start Stop, Heading Towards Roundabout. V1 Has Hit the Rear of V2 Causing V2 to Hit the Rear of V3.							Veh1, car, W -> E Veh2, car, W -> E Veh3, car, W -> E			Casualties 1 Vehicles 3	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

11-Nov-2015

15:08:49

A20 Leybourne/Ditton

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
75	Road No A228 Grid 568744E Section 161 Ref 158074N	SLIGHT	24/06/2015	4	16:35	L	Dry	Fine			
A228 Kings Hill by Pass Traffic Lights Near Entrance Road to Hermitage Farm, Leybourne, Kent									Tonbridge and Malling		
V1 and V2 Were on the A228 Kings Hill by Pass, Their Respective Journeys Meant They Were Travelling in the Direction of Kings Hill Towards M20. V2 was Stationary at the Traffic Lights when V1 Failed to Brake in Time and Collided into the Rear of V2. Minor Damage was Caused Due to Low Speed and Only Minor Injury to Driver of V1.							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	
76	Road No A20 Grid 569540E Section 133 Ref 158252N	SLIGHT	30/06/2015	3	18:39	L	Dry	Fine			
A20, London Road Jw Lunsford Lane, Larkfield, Kent									Tonbridge and Malling		
Veh 2 Stopped for a Red Light Ats Located on the A20 London Road, Larkfield. Whilst Waiting in a Stationary Position, was Struck from Behind by Veh 1. the Driver of Veh 1 was Breathalised at Road Side and Blew 'O'. Driver Stated Had Been Driving for Several Hours and Believed Lost Concentration Due to Fatigue.							Veh1, car, W -> E Veh2, car, W -> E			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight

 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective